



Part Number: TY1541-50

Part Description: Upper Feedback Actuator

## Specifications

|                              |                           |
|------------------------------|---------------------------|
| Product Families:            | Accessories               |
| Product Group:               | Engine Systems Accesories |
| Part Number                  | TY1541-50                 |
| Root Part Number             | TY1541-50                 |
| ATA Chapter 2 Digit          | 78                        |
| ATA Chapter 4 Digit          | 78-32                     |
| ATA Chapter 6 Digit          | 78-32-48                  |
| MFR / Manufacture -CAGE Code | Goodrich                  |
| Application                  | V2500                     |

## Repair

|                      |                         |
|----------------------|-------------------------|
| Part Number          | TY1541-50               |
| Description          | Upper Feedback Actuator |
| Repair Manual- CMM   | CMM                     |
| Bench Check & Advise | Yes                     |
| Repair               | Yes                     |
| Overhaul             | Yes                     |
| Repair Facility      | Hialeah                 |

## Logistics

|             |                         |
|-------------|-------------------------|
| Part Number | TY1541-50               |
| Description | Upper Feedback Actuator |

From sophisticated composite repairs for nacelles and stabilizers to intricate nose-to-tail flight control overhaul, 630 Aerospace offers a full range of services and payment approaches that accommodates each customer's mission requirements, business needs, and financial goals.

**630 Aerospace where quality is built in not inspected.**



Copyright 2021. 630 Aerospace Inc.

customerservice @630aerospace.com | +1-754-208-3737