



Part Number: TY1544-20

Part Description: Hand Wind Assembly

Specifications

Product Families:	Structures
Product Group:	Panels
Part Number	TY1544-20
Root Part Number	TY1544-20
ATA Chapter 2 Digit	78
ATA Chapter 4 Digit	78-32
ATA Chapter 6 Digit	78-32-41
MFR / Manufacture -CAGE Code	Goodrich
Application	V2500

Repair

Part Number	TY1544-20
Description	Hand Wind Assembly
Repair Manual- CMM	CMM
Bench Check & Advise	Yes
Repair	Yes
Overhaul	Yes
Repair Facility	Hialeah

Logistics

Part Number	TY1544-20
Description	Hand Wind Assembly

From sophisticated composite repairs for nacelles and stabilizers to intricate nose-to-tail flight control overhaul, 630 Aerospace offers a full range of services and payment approaches that accommodates each customer's mission requirements, business needs, and financial goals.

630 Aerospace where quality is built in not inspected.



Copyright 2021. 630 Aerospace Inc.

customerservice @630aerospace.com | +1-754-208-3737