



Part Number: 113T3100-402SP

Part Description: Outboard Trailing Edge Flap Assembly

Specifications

| Product Families: | Flight Controls and Surfaces |
|------------------------------|------------------------------|
| Product Group: | Flaps |
| Part Number | 113T3100-402SP |
| Root Part Number | 113T3100-402SP |
| ATA Chapter 2 Digit | 57 |
| ATA Chapter 4 Digit | 57-53 |
| ATA Chapter 6 Digit | 57-53-51 |
| MFR / Manufacture -CAGE Code | Boeing |
| Application | B757 |

Repair

| Part Number | 113T3100-402SP |
|----------------------|--------------------------------------|
| Description | Outboard Trailing Edge Flap Assembly |
| Repair Manual- CMM | СММ |
| Bench Check & Advise | Yes |
| Repair | Yes |
| Overhaul | Yes |
| Repair Facility | Miami Lakes |

Logistics

| Part Number | 113T3100-402SP |
|-------------|--------------------------------------|
| Description | Outboard Trailing Edge Flap Assembly |

From sophisticated composite repairs for nacelles and stabilizers to intricate nose-to-tail flight control overhaul, 630 Aerospace offers a full range of services and payment approaches that accommodates each customer's mission requirements, business needs, and financial goals.

630 Aerospace where quality is built in not inspected.



Copyright 2021. 630 Aerospace Inc.

customerservice @630aerospace.com | +1-754-208-3737