



Part Number: 286T5310-093

Part Description: Wire Bundle

Specifications

Product Families:	Harnesses
Product Group:	Engine Systems
Part Number	286T5310-093
Root Part Number	286T53XX-XXX
ATA Chapter 2 Digit	71
ATA Chapter 4 Digit	71-00
ATA Chapter 6 Digit	71-00-20
MFR / Manufacture -CAGE Code	Boeing
Application	B767

Repair

Part Number	286T5310-093
Description	Wire Bundle
Repair Manual- CMM	CMM
Bench Check & Advise	Yes
Repair	Yes
Repair Facility	Hialeah

Logistics

Part Number	286T5310-093
Description	Wire Bundle

From sophisticated composite repairs for nacelles and stabilizers to intricate nose-to-tail flight control overhaul, 630 Aerospace offers a full range of services and payment approaches that accommodates each customer's mission requirements, business needs, and financial goals.

630 Aerospace where quality is built in not inspected.



Copyright 2021. 630 Aerospace Inc.

customerservice @630aerospace.com | +1-754-208-3737