



Part Number: 314T4320-19

Part Description: Turbine Exhaust Plug Assembly

Specifications

Product Families:	Aircraft Interiors
Product Group:	Side Panels & Windows
Part Number	314T4320-19
Root Part Number	314T4320-XX
ATA Chapter 2 Digit	78
ATA Chapter 4 Digit	78-11
ATA Chapter 6 Digit	78-11-15
MFR / Manufacture -CAGE Code	Boeing
Application	CF6 - 50 & 80

Repair

Part Number	314T4320-19
Description	Turbine Exhaust Plug Assembly
Repair Manual- CMM	CMM
Bench Check & Advise	Yes
Repair	Yes
Overhaul	Yes
Repair Facility	Miami Lakes

Logistics

Part Number	314T4320-19
Description	Turbine Exhaust Plug Assembly

From sophisticated composite repairs for nacelles and stabilizers to intricate nose-to-tail flight control overhaul, 630 Aerospace offers a full range of services and payment approaches that accommodates each customer's mission requirements, business needs, and financial goals.

630 Aerospace where quality is built in not inspected.



Copyright 2021. 630 Aerospace Inc.

customerservice @630aerospace.com | +1-754-208-3737